

## **PRODUCT CHANGE NOTICE**

Issue Date: April 10, 2015


Notification No: PCN-1503009

## **Models Affected:**

• GLF-1002, GLF-1002B1, GLF-1002B2

## **Description of Change:**

Antronix has changed the labeling method for the date code on the models affected. The marking of the date code has changed from affixing an oval label to the body of the device to an automated printing method. The location of the main label has also moved from the F-female end of the device towards the F-male end of the device.



## **Additional Information:**

No impact to fit, form and function.

For any further information, please contact our office at (609) 860-0160.